



● Asbestos, TSP/metals sampling and ambient dust monitoring location	Building demolished	EAGLE ZINC OPERABLE UNIT 1 MONTGOMERY COUNTY, HILLSBORO, ILLINOIS
STATUS		
■ Debris remains, awaiting disposal	Decontamination in progress	
■ Awaiting asbestos abatement	Demolition in progress	
	—+—+— Former site railroad (removed)	
	■ Site boundary	
Basemap source: Esri		<b>DEMOLITION PROGRESS TRACKING</b> March 17 2015
EPA REGION 5 RAC 2   REVISION 0   March 2015		<b>ST</b> SulTRAC